



8134 - High Temperature Additive

Description:

Special clearcoat additive for hot and humid conditions.

Suitable Substrates:

Gen₂O

Mixing Ratio:

Add 5% to clearcoat before addition of hardener.

Raw Material:

Silicone oil solution

Important Remarks:

- For professional use only.
- Only use 8134 over Gen₂O in hot and humid conditions.
- Do not exceed the recommended dosage.

Cleaning of equipment: Clean after use with General Cleaning thinner.



Wear suitable protection

SDS:

See the safety data sheet

The Warnings displayed on the product labels should be followed.

The information contained here represents the current state of our knowledge and is intended as a guide to our products and their uses.